



**Landscape and Visual (L&V) Monitoring Report for  
Harbour Area Treatment Scheme Stage 2A  
(Operational Phase) (June 2022)**

Report No.: OT\_2022008

Prepared by :  \_\_\_\_\_

Tang Chung Hang, Frankie

Reviewed by :  \_\_\_\_\_

Lo Ting Yi, Ivy

## TABLE OF CONTENTS

1. Introduction .....	1
1.1. Background .....	1
1.2. Objectives.....	1
2. Landscape and Visual (L&V) .....	1
2.1. Monitoring Requirement.....	1
2.2. Monitoring Frequency.....	1
2.3. Monitoring Locations .....	2
2.4. Monitoring Methodology .....	2
3. L&V Monitoring Result .....	3
3.1. Inspection Result .....	3
3.2. Result Discussion .....	3

## LIST OF TABLES

Table 1.1	L&V Monitoring Location
Table 3.1	Summary of Reminders and observations for the 8 PTWs and SCISTW

## LIST OF APPENDICES

Appendix A	L&V Checklist
------------	---------------

## **1. Introduction**

### **1.1. Background**

1.1.1. Bestwise – Sun Fook Kong Joint Venture (the Contractors) appointed 3NV Technology Limited (3NV) to undertake the Landscape and Visual Monitoring for the Operational Phase of the “Enhancement of Deodourisation System at Stonecutters Island Sewage Treatment Works” (hereafter referred to as “the Project”).

1.1.2. The Project is part of the Harbour Area Treatment Scheme (HATS) Stage 2A. According to Environmental Permit No. EP-322/2008/G issued on 9th May 2014 by the Environmental Protection Department (hereinafter called EPD) to the Drainage Services Department (hereinafter called the DSD) as the Permit Holder and the EM&A Manual for the HATS Stage 2A, all landscape and visual mitigation measures shall be monitored monthly on-site during the first year of the Operational Phase at 8 preliminary treatment works (PTW) and the Stonecutters Island Sewage Treatment Works (SCISTW).

### **1.2. Objectives**

1.2.1. The objective is to monitor and audit the contractor’s landscape works, in particular, to ensure the existing trees retained on-site are being well preserved, tree transplanting and felling operations are being undertaken in accordance with the requirements, procedures, and specifications as stipulated in the contract and the approvals granted by concerned authorities, and all the newly planted vegetations are being maintained properly during the establishment period.

## **2. Landscape and Visual (L&V)**

### **2.1. Monitoring Requirement**

Under the EM&A Manual, Landscape and Visual Monitoring audit should be undertaken during the first year of the Operational Phase to ensure and check that the implementation and maintenance of landscape and visual mitigation measures are carried out by a Registered Landscape Architect (RLA).

### **2.2. Monitoring Frequency**

2.2.1. Site inspections should be undertaken once every month through the first year of the Operational Phase.

## 2.3. Monitoring Locations

2.3.1. Under this Project, there are 8 PTW and SCISTW that should be monitored. The details of the monitoring location are summarized in **Table 1.1**.

**Table 1.1 L&V Monitoring Locations**

No.	Description
1	North Point PTW
2	Wan Chai East PTW
3	Central PTW
4	Sandy Bay PTW
5	Cyberport PTW
6	Wah Fu PTW
7	Aberdeen PTW
8	Ap Lei Chau PTW
9	Stonecutter Island PTW

## 2.4. Monitoring Methodology

2.4.1. A Registered Landscape Architect is employed to monitor and audit the contractor's landscape works, in particular, to ensure the existing trees retained on-site are being well preserved, tree transplanting and felling operations are being undertaken in accordance with the requirements, procedures, and specifications as stipulated in the contract and the approvals granted by concerned authorities, and all the newly planted vegetations are being maintained properly during the establishment period by complete a checklist.



### 3. L&V Monitoring Result

#### 3.1. Inspection Result

3.1.1. Five new observations were found at Central PTW, Sandy Bay PTW, Wah Fu PTW and Stonecutter Island PTW. The completed checklist is shown in **Appendix A**.

#### 3.2. Result Discussion

3.2.1. Generally, all L&V mitigation measures listed in EM&A were applied at 8 PTWs and SCISTW. **Table 3.1** summarized the reminders and new observations of the 8 PTWs and SCISTW.

**Table 3.1 Summary of Reminders and New Observations for the 8 PTWs and SCISTW**

Monitoring Location	Reminders	New Observations
North Point PTW	<ol style="list-style-type: none"> <li>1. Carry out proper maintenance to plantings</li> <li>2. Increase the frequency of watering</li> </ol>	N/A
Wan Chai East PTW	<ol style="list-style-type: none"> <li>1. Carry out proper maintenance to plantings</li> <li>2. Increase the frequency of watering</li> </ol>	N/A
Central PTW	<ol style="list-style-type: none"> <li>1. Carry out proper maintenance to plantings</li> <li>2. Carry out remedial action or tree replacement of the unhealthy marked tree</li> </ol>	1. Poor condition of tree was observed.
Sandy Bay PTW	<ol style="list-style-type: none"> <li>1. Carry out proper maintenance to plantings</li> <li>2. Increase the frequency of watering</li> <li>3. Carry out remedial action or tree replacement of the unhealthy marked tree</li> </ol>	1. Poor condition of tree was observed.
Cyberport PTW	<ol style="list-style-type: none"> <li>1. Increase the frequency of</li> </ol>	N/A

	<p>watering</p> <p>2. Increase the maintenance of pot plants</p>	
Wah Fu PTW	<p>1. Carry out proper maintenance to plantings</p> <p>2. Increase the frequency of watering</p> <p>3. Close monitor on the condition of the marked tree</p>	<p>1. The condition of the tree for its large quantities of wilted leaves close to top of the tree crown.</p>
Aberdeen PTW	<p>1. Carry out proper maintenance to plantings</p> <p>2. Increase the frequency of watering</p> <p>3. Closely monitor the conditions of the pruned trees</p>	N/A
Ap Lei Chau PTW	<p>1. Carry out proper maintenance to plantings</p> <p>2. Increase the frequency of watering</p>	N/A
Stonecutter Island PTW	<p>1. Close monitoring or tree risk assessment may be required especially for trees T110 &amp; T109</p> <p>2. Review the situation and to remove the trees by the maintenance party to reduce the safety risk</p>	<p>1. Some trees adjacent to trees T110 &amp; T109 are severely tilted.</p> <p>2. Some tree branches span over driveway.</p>

## **Appendix A**

### **L&V Checklist**

**Landscape and Visual Impact Assessment Checklist for Site Audit – North Point PTW**

Inspection Date: 24 June, 2022  
Time: 10:15 am

Weather: Sunny/ Fine/ Cloudy/ Rainy  
Wind: Strong/ Breeze/ Light/ Calm

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	✓			

**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A


**New Observation:**

- N/A

**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings and was recommended to increase the frequency of watering.

**Photo Record:**



**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	<i>Xylem#</i>	4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Ap Lei Chau PTW**

Inspection Date: 24 June, 2022  
Time: 11:05am

Weather: Sunny/ Fine/Cloudy/ Rainy  
Wind: Strong/ Breeze/Light/Calm

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	✓			

**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A


**New Observation:**

- N/A

**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings and recommended to increase the frequency of watering.

**Photo Record:**



**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	<i>Xylem</i> #	4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Wah Fu PTW**

Inspection Date: 24 June, 2022  
Time: 11:15 am

Weather: Sunny/ Fine/ Cloudy / Rainy  
Wind: Strong/ Breeze/ Light/

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?		✓		Refer to new observation no.1
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?		✓		Refer to new observation no.1



**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A

**New Observation:**

1. The condition of the tree (shown in Figure 2) for its large quantities of wilted leaves close to top of the tree crown. The Contractor is recommended to carry out remedial action and close monitoring

**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings and recommended to increase the frequency of watering.

**Photo Record:**

Figure 1	Figure 2
	
Wah Fu PTW	Wah Fu PTW

**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem" #	4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Aberdeen PTW**

Inspection Date: 24 June, 2022  
Time: 11:05 am

Weather: Sunny/ Fine/Cloudy/ Rainy  
Wind: Strong/ Breeze/ Light/Calm

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	✓			

**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A


**New Observation:**

- N/A

**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings and recommended to closely monitor the conditions of the pruned trees. It is also recommended to increase the frequency of watering.
- Pruning of trees has been followed up as previously recommended.

**Photo Record:**



**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	<i>Xylem</i> #	4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Cyberport PTW**

Inspection Date: 24 June, 2022  
Time: 11:26 am

Weather: Sunny/ Fine/ Cloudy/ Rainy  
Wind: Strong/ Breeze/ Light/ Calm

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	✓			



**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A


**New Observation:**

- N/A

**Reminders:**

- The general housekeeping has been improved. Contractor was recommended to increase the frequency of watering. It is also recommended to increase the maintenance of pot plants.

**Photo Record:**



**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	<i>Xylem#</i>	4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Sandy Bay PTW**

**Inspection Date: 24 June, 2022**  
**Time: 11:32 pm**

**Weather: Sunny/ Fine/ Cloudy/ Rainy**  
**Wind: Strong/ Breeze/ Light/ Calm**

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?		✓		Refer to new observation no.1
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?		✓		Refer to new observation no.1

**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A



**New Observation:**

1. The health condition of marked tree (shown in Figure 2) is poor. The Contractor is recommended to carry out remedial action or tree replacement.


**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings and recommended to increase the frequency of watering.

**Photo Record:**

Figure 1	Figure 2
	
Sandy Bay PTW	Sandy Bay PTW

**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect		4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Central PTW**

**Inspection Date: 24 June, 2022**  
**Time: 11:49 pm**

**Weather: Sunny/ Fine/ Cloudy/ Rainy**  
**Wind: Strong/ Breeze/ Light/ Calm**

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?		✓		Refer to new observation no.1
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?		✓		Refer to new observation no.1



**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A



**New Observation:**

1. The health condition of marked tree (shown in Figure 2) is poor. The Contractor is recommended to carry out remedial action or tree replacement.


**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings.

**Photo Record:**

Figure 1	Figure 2
	
Central PTW	Central PTW

**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect		4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Wan Chai East PTW**

**Inspection Date: 24 June, 2022**  
**Time: 12:21 pm**

**Weather: Sunny/ Fine/ Cloudy/ Rainy**  
**Wind: Strong/ Breeze/ Light/ Calm**

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	✓			

**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A


**New Observation:**

- N/A

**Reminders:**

- Contractor was reminded to carry out proper maintenance to plantings and recommended to increase the frequency of watering.

**Photo Record:**



**Signature:**

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	<i>Xylem</i> #	4 <sup>th</sup> July 2022

**Landscape and Visual Impact Assessment Checklist for Site Audit – Stonecutters PTW**

Inspection Date: 24 June, 2022

Weather: Sunny/ Fine/ Cloudy/ Rainy

Time: 13:05 pm

Wind: Strong/ Breeze/ Light/ Calm

Item	Description	Yes	No	N/A	Actions / Remarks
<b>1</b>	<b>Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings</b>				
1.1	Is the aesthetic design match the surrounding environment?	✓			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
<b>2</b>	<b>Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening</b>				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	✓			
<b>3</b>	<b>Buffer Tree and Shrub Planting to screen proposed associated structures</b>				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	✓			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
<b>4</b>	<b>Reinstatement of disturbed area</b>				
4.1	Are the compensated planting covered the disturbed area?			✓	
<b>5</b>	<b>Others</b>				
5.1	Are existing trees retained on-site are being well preserved?		✓		Refer to new observation no.1 & 2.
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?		✓		Refer to new observation no.1 & 2.



**Summary / Remarks:**

**Follow up action taken by Contractor for previous comments:**

- No visible irregularities were found

**The contractor was reminded to rectify the following:**

- N/A

**New Observation:**




1. Some trees adjacent to trees T110 & T109 (shown in Figure 3) are severely tilted. The Contractor is recommended to carry out remedial action.
2. Some tree branches span over driveway (shown in Figure 3). The Contractor is recommended to carry out close monitoring or tree assessment.

**Reminders:**

- Vigour of some existing trees (e.g.T110 & T109) are found to be poor. Some adjacent trees are severely tilted. Close monitoring or tree risk assessment may be required.
- Die back of trees is noted. It is recommended that the maintenance party to review the situation and to remove the trees to reduce the safety risk if found to be required.

**Photo Record:**

Figure 1	Figure 2
	
Stonecutters Island PTW	Stonecutters Island PTW

Figure 3	Figure 4	
<p style="text-align: center;">Tree T110 &amp; T109</p> 		
Stonecutters Island PTW	Stonecutters Island PTW	

Signature:

		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	<i>Xylem#</i>	4 <sup>th</sup> July 2022