

Annex G

Baseline Landscape and Visual Monitoring Results






Contract No. DC/2007/23 Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Landscape Monitoring Locations in Wan Chai East

Resources Management




FILE: 0104887-HATS-LandIB-4.2-LRLCALocation-WCE DATE: 02/11/2009



Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Landscape Monitoring Locations in Central & Sai Ying Pun Environmental Resources Management



FILE: 0104887-HATS-LandIB-4.3-LRLCALocation-C DATE: 02/11/2009



FILE: 0104887-HATS-LandIB-4.4-LRLCALocation-SI DATE: 02/11/2009

Contract No. DC/2007/23

Harbour Area Treatment Scheme Stage 2A

Construction of Sewage Conveyance System from North Point to Stonecutters Island

Baseline Landscape Monitoring Locations in Stonecutters Island





LCA1 – Miscellaneous Urban Fringe Landscape



LCA2 –Civic Urban Waterfront Landscape



LCA3 – Transportation Corridor Landscape



LCA4 - Residential Urban Landscape



LCA5 - Industrial Urban Landscape

Landscape Character Area (LCA)

LCA1 – Miscellaneous Urban Fringe Landscape


LCA2 - Civic Urban Waterfront Landscape

LCA3 - Transportation Corridor Landscape

LCA4 - Residential Urban Landscape

LCA5 – Industrial Urban Landscape






FILE: 0104887-HATS-VisualB-4.6-VSRLocation-NP


DATE: 02/11/2009

Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations in North Point

Resources Management








Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations in Central & Sai Ying Pun





FILE: 0104887-HATS-VisualB-4.9-VSRLocation-SI DATE: 02/11/2009

Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations in Stonecutters Island Management

















R1.1, 01.1

Photo from EIA Report



Photo from EIA Report

Photo from Baseline Site Visit

Photo from Baseline Site Visit

Figure 4.10

Contract No. DC/2007/23 Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations and Results in North Point

Environmental Resources Management



Photo from EIA Report

C1.2, R1.3, R1.5, GIC1.5

GIC1.2 EXISTING CAR PARK.
PLANNED CUSTOMS HR TOWER

Photo from EIA Report



01.4 KING'S ROAD PLAYGROUND



Photo from Baseline Site Visit



T1.1 KING'S ROAD



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit




Photo from EIA Report



Photo from Baseline Site Visit












Photo from Baseline Site Visit






Photo from EIA Report

Photo from EIA Report

Photo from EIA Report

Photo from Baseline Site Visit










Photo from EIA Report



Photo from Baseline Site Visit






Photo from EIA Report

Photo from Baseline Site Visit




Photo from EIA Report



Photo from Baseline Site Visit

Figure 4.12

Contract No. DC/2007/23 Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations and Results in Wan Chai East







OU2.2



Photo from Baseline Site Visit



02.1



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit




Photo from EIA Report



Photo from Baseline Site Visit











C3.1, GIC3.2, CR3.1



Photo from Baseline Site Visit



CR3.2, CR3.3
Photo from EIA Report



Photo from Baseline Site Visit



CR3.4, CR3.5, CR3.6

Photo from EIA Report



Photo from Baseline Site Visit




Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Contract No. DC/2007/23

Harbour Area Treatment Scheme Stage 2A

Construction of Sewage Conveyance System from North Point to Stonecutters Island
Baseline Visual Monitoring Locations and Results in Central & Sai Ying Pun





Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report




Photo from Baseline Site Visit




Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit














Photo from EIA Report



Photo from Baseline Site Visit

Photo from EIA Report

Photo from Baseline Site Visit

GIC9.1 GOVERNMENT DOCKYARD



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report

Photo from Baseline Site Visit

Photo from EIA Report

Photo from Baseline Site Visit

Figure 4.16

Contract No. DC/2007/23 Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations and Results in Stonecutters Island







Photo from EIA Report



Photo from EIA Report



Photo from EIA Report



Photo from Baseline Site Visit



Photo from Baseline Site Visit



Photo from Baseline Site Visit



Photo from EIA Report



Photo from EIA Report



Photo from EIA Report





Photo from Baseline Site Visit




Photo from Baseline Site Visit



Contract No. DC/2007/23 Harbour Area Treatment Scheme Stage 2A Construction of Sewage Conveyance System from North Point to Stonecutters Island Baseline Visual Monitoring Locations and Results in Stonecutters Island





Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



Photo from EIA Report



Photo from Baseline Site Visit



