

1-hour TSP Monitoring Results

Station AM4

Date ^[1]	Start Time	Finish Time	Weather	TSP Concentration (µg/m ³)	Action Level (µg/m ³)	Limit Level (µg/m ³)	Site Conditions / Observations / Remarks	Temperature (°C)	Wind Speed * (m/s)	Sampler ID	Filter ID
06-Sep-11	12:00	13:00	Fine	120	352	500	Construction work in progress	31	<5	9315	1109
	13:02	14:02	Fine	112	352	500	Construction work in progress	31	<5	9315	1121
	14:25	15:25	Fine	193	352	500	Construction work in progress	31	<5	9315	1122
12-Sep-11	08:00	09:00	Sunny	134	352	500	Construction work in progress	29	<5	9315	1124
	09:02	10:02	Sunny	221	352	500	Construction work in progress	29	<5	9315	1125
	10:15	11:15	Sunny	190	352	500	Construction work in progress	29	<5	9315	1126
17-Sep-11	11:50	12:50	Fine	108	352	500	Construction work in progress	29	<5	9315	1128
	12:52	13:52	Fine	168	352	500	Construction work in progress	29	<5	9315	1129
	13:54	14:54	Fine	117	352	500	Construction work in progress	29	<5	9315	1130
23-Sep-11	12:00	13:00	Sunny	138	352	500	Construction work in progress	27	<5	9315	1142
	13:02	14:02	Sunny	137	352	500	Construction work in progress	27	<5	9315	1143
	14:10	15:10	Sunny	124	352	500	Construction work in progress	27	<5	9315	1144
30-Sep-11	08:00	09:00	Cloudy	90	352	500	Construction work in progress	28	<5	9315	1145
	09:02	10:02	Cloudy	83	352	500	Construction work in progress	28	<5	9315	1147
	10:05	11:05	Cloudy	106	352	500	Construction work in progress	28	<5	9315	1149
				Min.	83						
				Max.	221						
				Average	136						

[1] The schedule monitoring 29 September 2011 has been changed to 30 September 2011 due to adverse weather on 29 September 2011

* Please refer to the Wind Speed data in the EM&A Report