

1-hour TSP Monitoring Results

Station AM5

Date	Start Time	Finish Time	Weather	TSP Concentration ($\mu\text{g}/\text{m}^3$)	Action Level ($\mu\text{g}/\text{m}^3$)	Limit Level ($\mu\text{g}/\text{m}^3$)	Site Conditions / Observations / Remarks	Temperature ($^{\circ}\text{C}$)	Wind Speed * (m/s)	Sampler ID	Filter ID
05-May-11 [#]	-	-	-	-	-	-	-	-	-	-	-
	-	-	-	-	-	-	-	-	-	-	-
	-	-	-	-	-	-	-	-	-	-	-
11/May/11	15:35	16:35	Suuny	301	331.9	500	Grouting works	29	<5	Western Wholesale Food Market	581
	16:41	17:41	Sunny	76	331.9	500	Grouting works	29	<5	Western Wholesale Food Market	588
	17:43	18:43	Sunny	66	331.9	500	Grouting works	29	<5	Western Wholesale Food Market	589
17/May/11	08:00	09:00	Cloudy	221	331.9	500	Grouting works and shearing pin	23	<5	Western Wholesale Food Market	595
	13:30	14:30	Cloudy	57	331.9	500	Grouting works and shearing pin	23	<5	Western Wholesale Food Market	596
	14:50	15:50	Cloudy	51	331.9	500	Grouting works and shearing pin	23	<5	Western Wholesale Food Market	597
23/May/11	14:20	15:20	Fine	235	331.9	500	Grouting works and shearing pin	24	<5	Western Wholesale Food Market	601
	15:28	16:28	Fine	222	331.9	500	Grouting works and shearing pin	24	<5	Western Wholesale Food Market	602
	16:32	17:32	Fine	202	331.9	500	Grouting works and shearing pin	24	<5	Western Wholesale Food Market	603
27/May/11	08:00	09:00	Sunny	282	331.9	500	Grouting works and shearing pin	27	<5	Western Wholesale Food Market	607
	15:28	16:28	Sunny	215	331.9	500	Grouting works and shearing pin	27	<5	Western Wholesale Food Market	608
	16:32	17:32	Sunny	222	331.9	500	Grouting works and shearing pin	27	<5	Western Wholesale Food Market	609
			Min.	51							
			Max.	301							
			Average	179							

* Please refer the Wind Speed data to the EM&A Report

The schedule 1-hour TSP monitoring at AM5 was not conducted on 5 May due to the power supply failure of the equipment.