

1-hour TSP Monitoring Results

Station AM5

Date	Start Time	Finish Time	Weather	TSP Concentration (µg/m ³)	Action Level (µg/m ³)	Limit Level (µg/m ³)	Site Conditions / Observations / Remarks	Temperature (°C)	Wind Speed * (m/s)	Sampler ID	Filter ID
04-Jul-12	08:00	09:00	Fine	69	331.9	500	Operate of crane truck	29.6	<5	Western Wholesale Food Market	1100
	09:45	10:45	Fine	59	331.9	500	Operate of crane truck	29.6	<5	Western Wholesale Food Market	1101
	10:50	11:50	Fine	59	331.9	500	Operate of crane truck	29.6	<5	Western Wholesale Food Market	1102
10-Jul-12	13:00	14:00	Sunny	34	331.9	500	Loading and installing passenger hoist	29.9	<5	Western Wholesale Food Market	1107
	14:12	15:12	Sunny	26	331.9	500	Loading and installing passenger hoist	29.9	<5	Western Wholesale Food Market	1108
	15:37	16:37	Sunny	23	331.9	500	Loading and installing passenger hoist	29.9	<5	Western Wholesale Food Market	1109
16-Jul-12	13:54	14:54	Sunny	102	331.9	500	Loading and rock out	29.8	<5	Western Wholesale Food Market	1114
	15:00	16:00	Sunny	62	331.9	500	Loading and rock out	29.8	<5	Western Wholesale Food Market	1115
	16:11	17:11	Sunny	33	331.9	500	Loading and rock out	29.8	<5	Western Wholesale Food Market	1116
20-Jul-12	08:00	09:00	Hazy	106	331.9	500	Loading and rock out	30.3	<5	Western Wholesale Food Market	1122
	14:17	15:17	Hazy	71	331.9	500	Loading and rock out	30.3	<5	Western Wholesale Food Market	1123
	15:30	16:30	Hazy	81	331.9	500	Loading and rock out	30.3	<5	Western Wholesale Food Market	1124
26-Jul-12	HVS power supply failure										
	HVS power supply failure										
	HVS power supply failure										
				Min.	23						
				Max.	106						
				Average	60						

*Please refer to Wind Speed Data in EM&A Report