1-hour TSP Monitoring Results

Station AM5

Date	Start Time	Finish Time	Weather	TSP Concentration (μg/m³)	Action Level (μg/m³)	Limit Level (μg/m³)	Site Conditions / Observations / Remarks	Temperature (°C)	Wind Speed * (m/s)	Sampler ID	Filter ID
05-Nov-12	08:00	09:00	Fine	301	331.9	500	Blasting and rock out	24.1	<5	Western Wholesale Food Market	1250
05-Nov-12	10:13	11:13	Fine	151	331.9	500	Blasting and rock out	24.1	<5	Western Wholesale Food Market	1251
05-Nov-12	11:20	12:20	Fine	155	331.9	500	Blasting and rock out	24.1	<5	Western Wholesale Food Market	1252
09-Nov-12	08:00	09:00	Fine	161	331.9	500	Rock out	24.9	<5	Western Wholesale Food Market	1264
09-Nov-12	10:13	11:13	Fine	145	331.9	500	Rock out	24.9	<5	Western Wholesale Food Market	1265
09-Nov-12	11:20	12:20	Fine	114	331.9	500	Rock out	24.9	<5	Western Wholesale Food Market	1266
14-Nov-12	09:20	10:20	Fine	159	331.9	500	Rock out	23.4	<5	Western Wholesale Food Market	1271
14-Nov-12	10:25	11:25	Fine	147	331.9	500	Rock out	23.4	<5	Western Wholesale Food Market	1272
14-Nov-12	11:30	12:30	Fine	112	331.9	500	Rock out	23.4	<5	Western Wholesale Food Market	1273

112 Max. 301 161 Average

The scheduled monitoring on 20 and 26 November 2012 was not carried out due to electrical power supply problems Please refer to Wind Speed Data in EM&A Report