

## 1-hour TSP Monitoring Results

Station CM\_FM1, Western Wholesale Food Market

Date	Start Time	Finish Time	Weather	TSP Concentration ( $\mu\text{g}/\text{m}^3$ )	Action Level ( $\mu\text{g}/\text{m}^3$ )	Limit Level ( $\mu\text{g}/\text{m}^3$ )	Site Conditions / Observations / Remarks	Temperature ( $^{\circ}\text{C}$ )	Wind Speed (m/s)	Sampler ID	Filter ID
05/05/2011										N.A	N.A
05/05/2011							Power supply failure			N.A	N.A
05/05/2011										N.A	N.A
11/05/2011	15:35	16:35	Suuny	301	332	500	Grouting works	27.6	<5	Western Wholesale Food Market	581
11/05/2011	16:41	17:41	Sunny	76	332	500	Grouting works	27.6	<5	Western Wholesale Food Market	588
11/05/2011	17:43	18:43	Sunny	66	332	500	Grouting works	27.6	<5	Western Wholesale Food Market	589
17/05/2011	08:00	09:00	Cloudy	221	332	500	Grouting works and shearing pin	26.6	<5	Western Wholesale Food Market	595
17/05/2011	13:30	14:30	Cloudy	57	332	500	Grouting works and shearing pin	26.6	<5	Western Wholesale Food Market	596
17/05/2011	14:50	15:50	Cloudy	51	332	500	Grouting works and shearing pin	26.6	<5	Western Wholesale Food Market	597
23/05/2011	14:20	15:20	Fine	235	332	500	Grouting works and shearing pin	24.2	<5	Western Wholesale Food Market	601
23/05/2011	15:28	16:28	Fine	222	332	500	Grouting works and shearing pin	24.2	<5	Western Wholesale Food Market	602
23/05/2011	16:32	17:32	Fine	202	332	500	Grouting works and shearing pin	24.2	<5	Western Wholesale Food Market	603
27/05/2011	08:00	09:00	Sunny	282	332	500	Grouting works and shearing pin	26.7	<5	Western Wholesale Food Market	607
27/05/2011	15:28	16:28	Sunny	215	332	500	Grouting works and shearing pin	26.7	<5	Western Wholesale Food Market	608
27/05/2011	16:32	17:32	Sunny	222	332	500	Grouting works and shearing pin	26.7	<5	Western Wholesale Food Market	609
			<b>Min.</b>	<b>51</b>							
			<b>Max.</b>	<b>301</b>							
			<b>Average</b>	<b>179</b>							