

1-hour TSP Monitoring Results

Station CM FM1, Western Wholesale Food Market

Date	Start Time	Finish Time	Weather	TSP Concentration ($\mu\text{g}/\text{m}^3$)	Action Level ($\mu\text{g}/\text{m}^3$)	Limit Level ($\mu\text{g}/\text{m}^3$)	Site Conditions / Observations / Remarks	Temperature ($^{\circ}\text{C}$)	Wind Speed (m/s)	Sampler ID	Filter ID
19-Jul-13	08:57	09:57	Sunny	184	331.9	500	operation of excavator and loading	26.8	<5	Western Wholesale Food Market	1543
19-Jul-13	10:05	11:05	Sunny	68	331.9	500	operation of excavator and loading	26.8	<5	Western Wholesale Food Market	1556
19-Jul-13	11:09	12:09	Sunny	65	331.9	500	operation of excavator and loading	26.8	<5	Western Wholesale Food Market	1557
29-Jul-13	13:00	14:00	Sunny	294	331.9	500	operation of excavator and loading	28	<5	Western Wholesale Food Market	1563
29-Jul-13	14:12	15:12	Sunny	73	331.9	500	operation of excavator and loading	28	<5	Western Wholesale Food Market	1564
29-Jul-13	15:23	16:23	Sunny	70	331.9	500	operation of excavator and loading	28	<5	Western Wholesale Food Market	1565
				Min.	65						
				Max.	294						
				Average	125						

Remark: (2) The 1 hr and 24-hrs TSP monitoring were cancelled due to electricity safety problem from 28 June 2013 to 18 July 2013, the HVS failure. The 1 hr and 24-hrs TSP monitoring was rescheduled to 29 July 2013 from 25 July 2013 due to the HVS failure. The 24-hrs TSP monitoring result on 19 and 29 July 2013 were invalid because the HVS operated less than 24 hour: