1-hour TSP Monitoring Results

Station AM5

	Start	Finish	Weather	TSP Concentration	Action Level	Limit Level	Site Conditions /	Temperature	Wind Speed *	Sampler	Filter
Date	Time	Time		(µg/m³)	(μg/m ³)	(μg/m ³)	Observations / Remarks	(℃)	(m/s)	ID	ID
04-Apr-11	08:00	09:00	Fine	319	331.9	500	Grouting works	19.7	<5	Western Wholesale Food Market	542
	13:15	14:15	Fine	122	331.9	500	Grouting works	19.7	<5	Western Wholesale Food Market	544
	14:25	15:25	Fine	122	331.9	500	Grouting works	19.7	<5	Western Wholesale Food Market	545
08-Apr-11	08:00	09:00	Foggy	312	331.9	500	Grouting works	23.1	<5	Western Wholesale Food Market	550
	10:00	11:00	Foggy	167	331.9	500	Grouting works	23.1	<5	Western Wholesale Food Market	551
	11:03	12:03	Foggy	168	331.9	500	Grouting works	23.1	<5	Western Wholesale Food Market	552
14-Apr-11	08:00	09:00	Sunny	238	331.9	500	Grouting works	24.1	<5	Western Wholesale Food Market	558
	10:20	11:20	Sunny	130	331.9	500	Grouting works	24.1	<5	Western Wholesale Food Market	555
	11:24	12:24	Sunny	110	331.9	500	Grouting works	24.1	<5	Western Wholesale Food Market	559
20-Apr-11	08:00	09:00	Sunny	253	331.9	500	Grouting works	21.8	<5	Western Wholesale Food Market	564
	10:00	11:00	Sunny	258	331.9	500	Grouting works	21.8	<5	Western Wholesale Food Market	565
	11:10	12:10	Sunny	263	331.9	500	Grouting works	21.8	<5	Western Wholesale Food Market	566
26-Apr-11	08:00	09:00	Sunny	312	331.9	500	Grouting works	24.2	<5	Western Wholesale Food Market	571
	10:00	11:00	Sunny	117	331.9	500	Grouting works	24.2	<5	Western Wholesale Food Market	572
	11:10	12:10	Sunny	97	331.9	500	Grouting works	24.2	<5	Western Wholesale Food Market	573
29-Apr-11*	08:00	09:00	Cloudy	-	331.9	500	Grouting works	23.1	<5	Western Wholesale Food Market	578
	10:20	11:20	Cloudy	-	331.9	500	Grouting works	23.1	<5	Western Wholesale Food Market	579
	11:33	12:33	Cloudy	-	331.9	500	Grouting works	23.1	<5	Western Wholesale Food Market	580
			Min	97		•		-			•

Max.

Average

319

199

^{*} Please refer to the Wind Speed data in the EM&A Report
* The schedule1-hour TSP monitoring at AM5 was not conducted on 29 Apr due to the power supply failure of the equipment.