

1-hour TSP Monitoring Results

Station AM5

Date	Start Time	Finish Time	Weather	TSP Concentration (µg/m3)	Action Level (µg/m3)	Limit Level (µg/m3)	Site Conditions / Observations / Remarks	Temperature (°C)	Wind Speed (m/s)	Sampler ID	Filter ID
03-Apr-13	08:00	09:00	Cloudy	244	332	500	operation of excavator and loading	19.1	<5	Western Wholesale Food Market	1436
	13:36	14:36	Cloudy	141	332	500	operation of excavator and loading	19.1	<5	Western Wholesale Food Market	1437
	14:46	15:46	Cloudy	116	332	500	operation of excavator and loading	19.1	<5	Western Wholesale Food Market	1438
09-Apr-13	The timer for HVS was failure										
15-Apr-13	The timer for HVS was failure										
18-Apr-13	10:04	11:04	Fine	263	332	500	operation of excavator and loading	25.5	<5	Western Wholesale Food Market	1443
	15:33	16:33	Fine	51	332	500	operation of excavator and loading	25.5	<5	Western Wholesale Food Market	1444
	17:00	18:00	Fine	170	332	500	operation of excavator and loading	25.5	<5	Western Wholesale Food Market	1445
24-Apr-13	08:00	09:00	Fine	190	332	500	operation of excavator and loading	25.0	<5	Western Wholesale Food Market	1456
	13:37	14:37	Fine	78	332	500	operation of excavator and loading	25.0	<5	Western Wholesale Food Market	1457
	14:42	15:42	Fine	71	332	500	operation of excavator and loading	25.0	<5	Western Wholesale Food Market	1458
30-Apr-13	08:00	09:00	Fine	237	332	500	operation of excavator and loading	24.4	<5	Western Wholesale Food Market	1463
	13:15	14:15	Fine	41	332	500	operation of excavator and loading	24.4	<5	Western Wholesale Food Market	1464
	14:25	15:25	Fine	119	332	500	operation of excavator and loading	24.4	<5	Western Wholesale Food Market	1465
			Min.	41							
			Max.	263							
			Average	144							

*Wind Speed data is presented in the Meteorological Data Table

Note: The scheduled monitoring on 9 and 15 April 2013 was not carried out due to malfunction of timer for the HVS