

24-hour TSP Monitoring Results

Station CM_FM1, Western Wholesale Food Market

Date	Start		Finish		Weather	Filter Weight (g)		Elapsed Time Reading		Sampling Time (hrs)	Flow Rate (m ³ /min)			TSP Conc. (µg/m ³)	Action Level (µg/m ³)	Limit Level (µg/m ³)	Observations / Remarks	Sampler ID	Filter ID		
	Date	Time	Date	Time		Initial	Final	Initial	Final		Initial	Final	Average								
05-May-11	13:00	06-May-11	13:00	Sunny	Power supply failure (The contractor propose some mitigation methods to minimize the power supply failure to both HVS and tuck shop in FM)															N.A	N.A
11-May-11	18:45	12-May-11	18:45	Fine	2.7546	2.8321	2303.93	2327.93	24.00	1.0154	1.0154	1.0154	53	188.5	260	Grouting works	Western Wholesale Food Market	590			
17-May-11	15:15	18-May-11	15:15	Cloudy	2.7533	2.8731	2330.92	2354.92	24.00	1.1308	1.1308	1.1308	74	188.5	260	Grouting works	Western Wholesale Food Market	587			
23-May-11	17:40	24-May-11	17:40	Fine	2.7331	2.8264	2357.93	2381.93	27.60	1.0303	1.0303	1.0303	63	188.5	260	Grouting works	Western Wholesale Food Market	604			
27-May-11	12:05	28-May-11	12:05	Sunny	2.7524	3.0067	2384.93	2408.93	27.60	1.1238	1.1238	1.1238	157	188.5	260	Grouting works	Western Wholesale Food Market	610			
													Min.	53							
													Max.	157							
													Average	87							