1-hour TSP Monitoring Results

Date	Start Time	Finish Time	Weather	TSP Concentration (µg/m ³)	Action Level (µg/m ³)	Limit Level (µg/m ³)	Site Conditions / Observations / Remarks	Temperature (°C)	Wind Speed (m/s)	Sampler ID	Filter ID
05-Mar-14	10:10	11:10	Fine	197	332	500	loading,the monitoring was used laser dust temporary due to problem in electricity supply for the HVS	16.7	<5	LD-3B-002	N/A
05-Mar-14	11:10	12:10	Fine	191	332	500	loading,the monitoring was used laser dust temporary due to problem in electricity supply for the HVS	16.7	<5	LD-3B-002	N/A
11-Mar-14	13:40	14:40	Fine	137	332	500	loading,the monitoring was used laser dust temporary due to problem in electricity supply for the HVS	15	<5	LD-3B-002	N/A
11-Mar-14	14:40	15:40	Fine	141	332	500	loading,the monitoring was used laser dust temporary due to problem in electricity supply for the HVS	15	<5	LD-3B-002	N/A
11-Mar-14	15:40	16:40	Fine	145	332	500	loading,the monitoring was used laser dust temporary due to problem in electricity supply for the HVS	15	<5	LD-3B-002	N/A
17-Mar-14	10:54	11:54	Fine	217	332	500	Loading concrete	20.4	<5	Western Wholesale Food Market	1819
17-Mar-14	13:40	14:40	Fine	258	332	500	Loading concrete	20.4	<5	Western Wholesale Food Market	1820
17-Mar-14	14:56	15:56	Fine	212	332	500	Loading concrete	20.4	<5	Western Wholesale Food Market	1821
21-Mar-14	08:00	09:00	Fine	290	332	500	Loading concrete	16.5	<5	Western Wholesale Food Market	1844
21-Mar-14	10:50	11:50	Fine	185	332	500	Loading concrete	16.5	<5	Western Wholesale Food Market	1845
21-Mar-14	12:00	13:00	Fine	171	332	500	Loading concrete	16.5	<5	Western Wholesale Food Market	1846
27-Mar-14	13:20	14:20	Fine	299	332	500	Loading concrete	23.5	<5	Western Wholesale Food Market	1851
27-Mar-14	14:28	15:28	Fine	56	332	500	Loading concrete	23.5	<5	Western Wholesale Food Market	1852
27-Mar-14	15:35	16:35	Fine	67	332	500	Loading concrete	23.5	<5	Western Wholesale Food Market	1853
			Average Maximum	184 299							

Maximum 299 Minimum 56