

1-hour TSP Monitoring Results

Station CM_AB1a, The Hong Kong Ice and Cold Storage (Aberdeen)

Date	Start Time	Finish Time	Weather	TSP Concentration ($\mu\text{g}/\text{m}^3$)	Action Level ($\mu\text{g}/\text{m}^3$)	Limit Level ($\mu\text{g}/\text{m}^3$)	Site Conditions / Observations / Remarks	Temperature ($^{\circ}\text{C}$)	Wind Speed (m/s)	Sampler ID	Filter ID
06/09/2010	12:52	13:52	Sunny	96	282.5	500	No major construction works	29.3	<5	LD-3B-001	N/A
	13:52	14:52	Sunny	96	282.5	500	No major construction works	29.3	<5	LD-3B-001	N/A
	14:52	15:52	Sunny	84	282.5	500	No major construction works	29.3	<5	LD-3B-001	N/A
10/09/2010	09:08	10:08	Sunny	43	282.5	500	Grouting works	28.1	<5	LD-3B-001	N/A
	10:08	11:08	Sunny	26	282.5	500	Grouting works	28.1	<5	LD-3B-001	N/A
	11:08	12:08	Sunny	30	282.5	500	Grouting works	28.1	<5	LD-3B-001	N/A
16/09/2010	09:06	10:06	Sunny	15	282.5	500	Grouting works	28.9	<5	LD-3B-001	N/A
	10:06	11:06	Sunny	12	282.5	500	Grouting works	28.9	<5	LD-3B-001	N/A
	11:06	12:06	Sunny	12	282.5	500	Grouting works	28.9	<5	LD-3B-001	N/A
22/09/2010	13:12	14:12	Sunny	44	282.5	500	Grouting works	25.4	<5	LD-3B-001	N/A
	14:12	15:12	Sunny	37	282.5	500	Grouting works	25.4	<5	LD-3B-001	N/A
	15:12	16:12	Sunny	38	282.5	500	Grouting works	25.4	<5	LD-3B-001	N/A
28/09/2010	09:05	10:05	Sunny	34	282.5	500	Grouting works	28.6	<5	LD-3B-001	N/A
	10:05	11:05	Sunny	21	282.5	500	Grouting works	28.6	<5	LD-3B-001	N/A
	11:05	12:05	Sunny	19	282.5	500	Grouting works	28.6	<5	LD-3B-001	N/A
				Min.	12						
				Max.	96						
				Average	41						