

Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
01-Aug-11	10:44	11:14	Sunny	59	61	53	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	29.5	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
11-Aug-11	10:44	11:14	Sunny	54	56	51	Mud out						
17-Aug-11	10:36	11:06	Sunny	57	58	52	Operation excavator	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	28.7	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
23-Aug-11	10:36	11:06	Sunny	58	59	54	Blasting	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	29.8	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2385180
29-Aug-11	10:35	11:05	Foggy	61	63	55	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	30.6	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2385180
				Min.	54								
				Max.	61								

Remark: Free-field measurement, +3dB correction.