

Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
02-Feb-11	10:22	10:52	Fine	54	56	50	No major construction works	Operation of excavator and loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	14.8	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
08-Feb-11	14:06	14:36	Fine	52	54	50	No major construction works	Operation of excavator and loading activities from the construction site near Cyberport	Free-field measurement, +3dB correction.	19.6	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
14-Feb-11	11:05	11:35	Fine	54	56	50	Rocks out	Operation of excavator and loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	10.6	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
24-Feb-11	11:05	11:35	Fine	61	61	55	Rocks out and excavation	Loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	18.8	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
				Min.	52								
				Max.	61								

Remark: Free-field measurement, +3dB correction.