

Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
06-Jul-11	10:50	11:20	Sunny	61	64	55	No major construction works	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	29.7	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
14-Jul-11	10:38	11:08	Cloudy	61	64	55	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	27.1	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
20-Jul-11	10:27	10:57	Cloudy	61	64	55	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	27.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
26-Jul-11	15:01	15:31	Sunny	61	64	55	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	30.1	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
				Min.	61								
				Max.	61								

Remark: Free-field measurement, +3dB correction.