

Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
01-Jun-11	10:06	10:36	Sunny	61	64	55	No major construction works	Loading activities and operating hydraulic excavator from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	27.9	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
07-Jun-11	14:30	15:00	Sunny	61	64	55	No major construction works	Loading activities and operating hydraulic excavator from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	29.6	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
13-Jun-11	11:11	11:41	Sunny	61	64	55	Rock Excavation and loading	Loading activities and operating hydraulic excavator from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	28.7	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
23-Jun-11	10:11	10:41	Cloudy	61	64	55	No major construction works	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	28.0	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
29-Jun-11	10:31	11:01	Cloudy	61	64	55	No major construction works	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	26.5	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
				Min.	61								
				Max.	61								