Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction			_			a
				Leq *	L10	L90	Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (℃)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
02-Mar-11	15:50	16:20	Sunny	57	58	54	Rocks out and excavation	Loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	18.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2656516
08-Mar-11	15:50	16:20	Sunny	59	61	53	Rocks out and excavation	the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	15.5	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2656516
14-Mar-11	15:06	15:36	Fine	60	63	56	No major construction works	Loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	22.4	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2656516
24-Mar-11	10:28	10:58	Cloudy	55	56	52	No major construction works	Loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	16.8	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2656516
30-Mar-11	11:18	11:48	Sunny	67	68	61	No major construction works	Loading activities from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	18.1	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2656516
			Min.	55									
			Max.	67									

Remark: Free-field measurement, +3dB correction.