Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction	Other Noise	Remarks	Temp.	Wind Speed	Noise Meter	Calibrator
				Leq *	L10	L90	Noise Source(s)	Source(s) Observed	Heiliaiks	(℃)	(m/s)	Model / ID	Model / ID
05-May-11	10:49	11:19	Sunny	59	60	55	No major construction works	Loading activities and operating hydraulic excavaior from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	23.6	< 5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
11-May-11	10:36	11:06	Sunny	62	65	55	No major construction works	operating hydraulic excavaior from the	Free-field measurement, +3dB correction.	29.3	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
17-May-11	10:45	11:15	Drizzle	59	62	52	No major construction works	Loading activities and operating hydraulic excavaior from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	25.6	< 5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
23-May-11	10:09	10:39	Cloudy	61	64	55	Grouting	Loading activities and operating hydraulic excavaior from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	24.2	< 5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
		•	Min.	59		•							
			Max.	62									

Remark: Free-field measurement, +3dB correction.