

Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
01-Nov-11	13:55	14:25	Sunny	57	58	53	Works inside noise enclosure	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	24.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
10-Nov-11	15:31	16:01	Cloudy	57	59	53	Operation of excavator and gantry	Loading from the construction site near Cyberport PTW and operation of excavator	Free-field measurement, +3dB correction.	19.4	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
15-Nov-11	10:41	11:11	Sunny	55	57	51	Operation of gantry	Loading from the construction site near Cyberport PTW and operation of excavator	Free-field measurement, +3dB correction.	23.5	<5	B&K 2238 S/N : 2381580	B&K 4231 S/N: 2385180
21-Nov-11	10:37	11:07	Sunny	59	60	53	Operation of gantry	Loading from the construction site near Cyberport PTW and operation of excavator	Free-field measurement, +3dB correction.	21.5	<5	B&K 2238 S/N : 2381580	B&K 4231 S/N: 2385180
				Min.	55								
				Max.	59								

Remark: Free-field measurement, +3dB correction.