

Daytime Noise Monitoring Results - Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s)	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
06-Oct-11	10:41	11:11	Cloudy	61	64	52	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	25.2	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
18-Oct-11	10:51	11:21	Sunny	56	57	52	Mud out	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	24.7	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
24-Oct-11	11:00	11:30	Sunny	58	59	55	Works inside noise enclosure	Excavation from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	25.7	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 2385180
				Min.	56								
				Max.	61								

[1] The monitoring data was cancelled due to rain on 12 Oct

[2] Free-field measurement, +3dB correction.