

Daytime Noise Monitoring Results -- Normal weekday

Station M6a, Aegean Terrace

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s)	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed	Noise Meter Model / ID	Calibrator Model / ID
				Leq *	L10	L90							
05-Jan-12	17:37	18:07	Cloudy	54	56	49	Rock out and drilling	Loading from the construction site near Cyberport PTW and operation of excavator	Free-field measurement, +3dB correction.	11.0	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2385180
10-Jan-12	10:58	11:28	Cloudy	58	60	51	Loading	Loading from the construction site near Cyberport PTW and operation of excavator	Free-field measurement, +3dB correction.	15.9	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2385180
16-Jan-12	10:41	11:11	Cloudy	62	66	51	Operation of mobile crane	Loading from the construction site near Cyberport PTW and an ideal vehicle parking near roadside	Free-field measurement, +3dB correction.	15.7	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
27-Jan-12	10:21	10:51	Cloudy	57	58	51	Operation of mobile crane	Loading from the construction site near Cyberport PTW and an ideal vehicle parking near roadside	Free-field measurement, +3dB correction.	14.7	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
31-Jan-12	11:05	11:35	Fine	62	56	51	Loading	Loading from the construction site near Cyberport PTW	Free-field measurement, +3dB correction.	15.1	<5	B&K 2238 S/N : 2684502	B&K 4231 S/N: 2656516
				Min.	54								
				Max.	62								

Remark: Free-field measurement, +3dB correction.