Daytime Noise Monitoring Results -- Normal weekday

Max.

Station M3, Kwan Yick building(*)

| Date | Start Time | End Time | Weather | Noise level (dB(A)), 30 min | | | Major | Other Noise | Remarks | Temp. | Wind | Noise Meter | Calibrator |
|-----------|---------------|-------------|---------|-----------------------------|---------|--------------|---------------------------|------------------------|-------------------------|---------------|--------------|------------------------------|----------------------------------|
| | | | | Leq | L10 | L90 | Construction | Source(s) Observed | nemarks | (°C) | Speed | Model / ID | Model / ID |
| 04-Jul-11 | 10:25 | 10:55 | Sunny | 68 | 70 | 67 | Excavation (Near site) | Traffic Noise | N.A | 32.0 | 0.2 | RION- NL31 (S/N 00983400) | RION - NC73 (S/N 10997142) |
| 15-Jul-11 | 14:30 | 15:00 | Cloudy | 68 | 70 | 67 | Excavation (Near site) | Traffic Noise | N.A | 28.0 | 0.2 | RION- NL31 (S/N 00983400) | RION - NC73 (S/N 10997142) |
| 21-Jul-11 | 14:32 | 15:02 | Fine | 68 | 69 | 66 | Excavation (Near site) | Traffic Noise | N.A | 31.0 | 0.2 | RION- NL31 (S/N 00983400) | RION - NC73 (S/N 10997142) |
| 27-Jul-11 | 10:25 | 10:55 | Fine | 68 | 69 | 66 | Excavation (Near site) | Traffic Noise | N.A | 30.0 | 0.3 | RION- NL31 (S/N 00983400) | RION - NC73 (S/N 10997142) |
| | | | Min. | 68 | Remark: | : (*): The d | ata were provid | ed by Contract No. DC/ | 2007/23. Calibration ce | rtificates fo | or the noise | meter(s) and cali | brator(s) used |

68 Remark: (*): The data were provided by Contract No. DC/2007/23. Calibration certificates for the noise meter(s) and calibrator(s) used were included in the corresponding Monthly EM&A Report for this Contract