

Restricted Hours Noise Monitoring Results -- Daytime on Public Holiday

Station M5a, Chuk Lam Ming Tong

| Date | Start Time | End Time | Weather | Noise level (dB(A)), 5 min | | | Major Construction | Other Noise Source(s) Observed | Remarks | Temp. (°C) | Wind Speed | Noise Meter Model / ID | Calibrator Model / ID |
|-----------|------------|----------|---------|----------------------------|-----|-----|-----------------------------|-------------------------------------|---------|------------|------------|------------------------|-----------------------|
| | | | | Leq | L10 | L90 | | | | | | | |
| 18-Dec-11 | 16:44 | 16:59 | Cloudy | 59 | 61 | 54 | No major construction works | Road traffic noise at San Wan Drive | N.A | 16.1 | <5 | B&K 2238 S/N : 2684502 | B&K 4231 S/N: 2385180 |
| 26-Dec-11 | 16:44 | 16:59 | Cloudy | 63 | 64 | 54 | No major construction works | Road traffic noise at San Wan Drive | N.A | 15.8 | <5 | B&K 2238 S/N : 2684502 | B&K 4231 S/N: 2385180 |
| | | | | Min. | 59 | | | | | | | | |
| | | | | Max. | 63 | | | | | | | | |

Restricted Hours Noise Monitoring Results -- Evening time

Station M5a, Chuk Lam Ming Tong

| Date | Start Time | End Time | Weather | Noise level (dB(A)), 5 min | | | Major Construction | Other Noise Source(s) Observed | Remarks | Temp. (°C) | Wind Speed | Noise Meter Model / ID | Calibrator Model / ID |
|-----------|------------|----------|---------|----------------------------|-----|-----|------------------------------|--|---|------------|------------|------------------------|-----------------------|
| | | | | Leq | L10 | L90 | | | | | | | |
| 07-Dec-11 | 22:45 | 23:00 | Cloudy | 63 | 59 | 49 | Operation of excavator | Road traffic at San Wan Drive and ideal cement truck parking near the football playground | According to contractor, general construction works was in process accordance to CNP. | 22.3 | <5 | B&K 2238 S/N : 2684502 | B&K 4231 S/N: 2385180 |
| 21-Dec-11 | 22:45 | 23:00 | Fine | 61 | 59 | 49 | Works inside noise enclosure | Road traffic at San Wan Drive and ideal police patrol car parking near the football playground | According to contractor, general construction works was in process accordance to CNP. | 19.5 | <5 | B&K 2238 S/N : 2684502 | B&K 4231 S/N: 2656516 |
| | | | | Min. | 61 | | | | | | | | |
| | | | | Max. | 63 | | | | | | | | |