## Restricted Hours Noise Monitoring Results -- Evening Time and Daytime on Public Holiday

Station M5a, Chuk Lam Ming Tong

| Date Start End |       |       | Weather | Noise level (dB(A)), 5 min |      |      | Major        | Other Noise                         | Remarks | Temp. | Wind  | Noise Meter               | Calibrator               |
|----------------|-------|-------|---------|----------------------------|------|------|--------------|-------------------------------------|---------|-------|-------|---------------------------|--------------------------|
| Date           | Time  | Time  | weather | Leq                        | L10  | L90  | Construction | Source(s)                           | nemarks | (℃)   | Speed | Model / ID                | Model / ID               |
| 23-Dec-12      | 14:03 | 14:18 | Fine    | 67.3                       | 68.9 | 53.6 | Loading      | Road traffic noise at San Wan Drive | N.A     | 13.3  | <5    | B&K 2238 S/N :<br>2661357 | B&K 4231 S/N:<br>2671470 |
|                |       |       | Min.    | 67.3                       |      |      |              |                                     |         |       |       |                           |                          |
|                |       |       | Max.    | 67.3                       |      |      |              |                                     |         |       |       |                           |                          |

## Restricted Hours Noise Monitoring Results -- Evening time

Station M5a, Chuk Lam Ming Tong

| Time   Time   Time   Time   Leq   L10   L90   Construction   Source(s)   According to contractor, general construction   Wan Drive   Works in tunnel   Road traffic at San Wan Drive   Works was in process accordance to CNP.   According to contractor, general construction works was in process accordance to CNP.   According to contractor, general construction works was in process accordance to CNP.   According to contractor, general construction works was in process   Road traffic at San Wan Drive   According to contractor, general construction works was in process   Road traffic at San Wan Drive   Road traffic at San Wan Drive   According to contractor, general construction works was in process   Road traffic at San Wan Drive   Road traffic at San Wan Driv | Date      | Start<br>Time | End<br>Time | Weather | Noise level (dB(A)), 5 min |      |      | Major           | Other Noise | Remarks  | Temp. | Wind  | Noise Meter | Calibrator               |
|--|-----------|---------------|-------------|---------|----------------------------|------|------|-----------------|-------------|--|-------|-------|-------------|--------------------------|
| 07-Dec-12   22:45   23:00   Fine   62.1   63.8   49.9   Works in tunnel   Road traffic at San Wan Drive   Road traffic at San Works was in process accordance to CNP.   According to contractor, general construction works was in process accordance to CNP.   According to contractor, general construction works was in process accordance to CNP.   According to contractor, general construction works was in process   18.6   49.0   Works in tunnel   Road traffic at San Wan Drive   Road traffic at San Wan Drive   18.6   45   B&K 2238 S/N   B&K 42:38 S/N   B&K  |           |               |             |         | Leq                        | L10  | L90  | Construction    | Source(s)   | nemarks  | (℃)   | Speed | Model / ID  | Model / ID               |
| 27-Dec-12 22:45 23:00 Fine 61.3 63.2 49.0 Works in tunnel Road traffic at San Wan Drive contractor, general construction works was in process 18.6 <5 B&K 2238 S/N: B&K 42: 3000   | 07-Dec-12 | 22:45         | 23:00       | Fine    | 62.1                       | 63.8 | 49.9 | Works in tunnel |             | contractor,<br>general<br>construction<br>works was in<br>process<br>accordance to | 18.4  | <5    |             | B&K 4231 S/N:<br>3003246 |
| accordance to CNP.   | 27-Dec-12 | 22:45         | 23:00       | Fine    | 61.3                       | 63.2 | 49.0 | Works in tunnel |             | contractor,<br>general<br>construction<br>works was in<br>process<br>accordance to | 18.6  | <5    |             | B&K 4231 S/N:<br>3003246 |

Min. 61.3 Max. 62.1