Restricted Hours Noise Monitoring Results -- Evening time Station M5a, Chuk Lam Ming Tong

| Date | Start Time | End Time | Weather | Noise level (dB(A)), 5 min | | | Major | | | | | | |
|-----------|---------------|-------------|---------|----------------------------|-----|-----|---|--------------------------------------|---|---------------|------------------------|---------------------------|--------------------------|
| | | | | Leq | L10 | L90 | Construction Noise Source(s) Observed | Other Noise Source(s) Observed | Remarks | Temp. (°C) | Wind Speed (m/s) | Noise Meter Model / ID | Calibrator Model / ID |
| 03-Oct-13 | 22:45 | 23:00 | Fine | 61 | 66 | 51 | Works in tunnel | Road traffic at San Wan Drive | According to contractor, general construction works was in process accordance to CNP. | 26.0 | <5 | B&K 2238 S/N : 2684503 | B&K 4231 S/N: 3004068 |
| 29-Oct-13 | 22:45 | 23:00 | Fine | 62 | 64 | 50 | Works in tunnel | Road traffic at San Wan Drive | According to contractor, general | 23.7 | <5 | B&K 2238 S/N : 2684503 | B&K 4231 S/N: 3004068 |
| | • | • | Min. | 61 | | • | • | • | | | | | • |
| | | | Max. | 62 | | | | | | | | | |