

## Night time Noise Monitoring Results

### Station M5a, Chuk Lam Ming Tong(near entrance )

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq	L10	L90							
07/08/2014-a	23:00	23:05	Cloudy	60	60	52	No major construction workd on surface	Traffic noise at San Wan Drive	N.A	29.0	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07/08/2014-b	23:05	23:10	Cloudy	56	60	52						B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07/08/2014-c	23:10	23:15	Cloudy	56	57	52						B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07-Aug-14	23:00	23:15	Cloudy	57	59	52	No major construction workd on surface	Traffic noise at San Wan Drive	N.A	29.0	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
28/08/2014-a	23:00	23:05	Fine	63	65	51	No major construction workd on surface	Traffic noise at San Wan Drive	N.A	29.5	<5	B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
28/08/2014-b	23:05	23:10	Fine	63	65	51						B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
28/08/2014-c	23:10	23:15	Fine	64	65	52						B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
28-Aug-14	23:00	23:15	Fine	63	65	51	No major construction workd on surface	Traffic noise at San Wan Drive	N.A	29.5	<5	B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
				<b>Max</b>	<b>64</b>								
				<b>Min</b>	<b>56</b>								
				<b>Average</b>	<b>60</b>								