

Evening time Noise Monitoring Results

Station M5, Chuk Lam Ming Tong (near entrance)

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq	L10	L90							
07/08/2014-a	22:45	22:50	Cloudy	61	64	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	29.0	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07/08/2014-b	22:50	22:55	Cloudy	62	63	52				29.0	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004038
07/08/2014-c	22:55	23:00	Cloudy	63	64	52				29.0	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07-Aug-14	22:45	23:00	Cloudy	62	63	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	29.0	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
28/08/2014-a	22:45	22:50	Fine	62	63	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	29.5	<5	B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
28/08/2014-b	22:50	22:55	Fine	62	63	52				29.5	<5	B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004038
28/08/2014-c	22:55	23:00	Fine	62	65	51				29.5	<5	B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
28-Aug-14	22:45	23:00	Fine	62	63	51	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	29.5	<5	B&K 2238 S/N : 2800932	B&K 4231 S/N: 3004068
				Max	63								
				Min	61								
				Average	62								