Evening time Noise Monitoring Results

Station M5, Chuk Lam Ming Tong(near entrance)

Date	Start Time	End Time	Weather	Noise level (dB(A))			Major						
				Leq	L10	L90	Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
07/03/2014-a	22:45	22:50	Fine	57	60	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	30.5	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07/03/2014-b	22:50	22:55	Fine	60	62	52				30.5	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004038
07/03/2014-c	22:55	23:00	Fine	53	54	51				30.5	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
03-Jul-14	22:45	23:00	Fine	58	64	51	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	30.5	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07/30/2014-a	22:45	22:50	Fine	62	64	53	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	30.4	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
07/30/2014-b	22:50	22:55	Fine	60	62	52				30.4	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004038
07/30/2014-c	22:55	23:00	Fine	58	60	52				30.4	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30-Jul-14	22:45	23:00	Fine	60	64	51	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	30.4	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068

Max. 62 Min. 53 Average 58