

## Night time Noise Monitoring Results

### Station M5a, Chuk Lam Ming Tong(near entrance)

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq	L10	L90							
11/09/2014-a	23:00	23:05	Fine	63	64	52	No major construction workd on surface	Traffic noise at San Wan Drive	N.A	30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
11/09/2014-b	23:05	23:10	Fine	65	67	52	No major construction workd on surface			30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
11/09/2014-c	23:10	23:15	Fine	66	68	52	No major construction workd on surface			30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
11-Sep-14	23:00	23:15	Fine	65	66	52	No major construction workd on surface	Traffic noise at San Wan Drive	N.A	30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30/09/2014-a	23:00	23:05	Fine	62	63	53	Loading works under the shaft inside noise enclosure	Traffic noise at San Wan Drive	N.A	29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30/09/2014-b	23:05	23:10	Fine	64	65	53	Loading works under the shaft inside noise enclosure			29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30/09/2014-c	23:10	23:15	Fine	61	63	53	Loading works under the shaft inside noise enclosure			29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30-Sep-14	23:00	23:15	Fine	62	64	53	Loading works under the shaft inside noise enclosure	Traffic noise at San Wan Drive	N.A	29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068

<b>Max</b>	<b>66</b>
<b>Min</b>	<b>61</b>
<b>Average</b>	<b>64</b>