

Evening time Noise Monitoring Results

Station M5, Chuk Lam Ming Tong(near entrance)

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq	L10	L90							
11/09/2014-a	22:45	22:50	Fine	62	64	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
11/09/2014-b	22:50	22:55	Fine	64	65	52				30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004038
11/09/2014-c	22:55	23:00	Fine	66	67	52				30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
11-Sep-14	22:45	23:00	Fine	64	65	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	30.3	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30/09/2014-a	22:45	22:50	Fine	60	64	53	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process	29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30/09/2014-b	22:50	22:55	Fine	60	63	52				29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004038
30/09/2014-c	22:55	23:00	Fine	64	65	53				29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
30-Sep-14	22:45	23:00	Fine	61	64	52	Loading works under the shaft	Road traffic at San Wan Drive	According to contractor, general construction works was in process accordance to CNP.	29.6	<5	B&K 2238 S/N : 2684503	B&K 4231 S/N: 3004068
				Max	66								
				Min	60								
				Average	62								