

Daytime Noise Monitoring Results

Station NM2

Date	Start Time	End Time	Weather	Noise level (dB(A)), 30 min			Major Construction Noise Source(s) Observed	Other Noise Source(s) Observed	Remarks	Temp. (°C)	Wind Speed (m/s)	Noise Meter Model / ID	Calibrator Model / ID
				Leq	L10	L90							
02-Aug-11	13:30	14:00	Sunny	73	74	72	Lifting, steel bending (Near site)	Traffic noise	-	31	0.4	RION- NL31 (S/N 00983400)	RION - NC73 (S/N 10997142)
08-Aug-11	13:21	13:51	Sunny	72	73	71	Lifting, excavation (Near site)	Traffic noise	-	32	0.2	RION- NL31 (S/N 00983400)	RION - NC73 (S/N 10997142)
19-Aug-11	14:22	14:52	Sunny	73	74	72	Lifting (Near site)	Traffic noise	-	31	0.5	RION- NL31 (S/N 00983400)	RION - NC73 (S/N 10997142)
25-Aug-11	09:20	09:50	Sunny	73	74	73	Lifting, steel bending (Near site)	Traffic noise	-	31	0.2	RION- NL31 (S/N 00983400)	RION - NC73 (S/N 10997142)
31-Aug-11	09:29	09:59	Sunny	73	74	72	Lifting, excavation (Near site)	Traffic noise	-	31	0.2	RION- NL31 (S/N 00983400)	RION - NC73 (S/N 10997142)
				Min.	72								
				Max.	73								